

# Water Testing Results - Gold Beach High School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
<b>Main Building and Gym</b>			
District Office	19720200-001SF	4/26/2021	80
Room 1	19720200-002KF	4/26/2021	2
Boys Bathroom N Hall West	19720200-003BF	4/26/2021	10
Boys Bathroom N Hall East	19720200-004BF	4/26/2021	4
Water Bottle Filler Drinking Station	19720200-005DW	4/26/2021	ND
Girls Bathroom Middle Hall NW	19720200-006BF	4/26/2021	54
Girls Bathroom Middle Hall Middle	19720200-007BF	4/26/2021	83
Girls Bathroom Middle Hall NE	19720200-008BF	4/26/2021	32
Staff Lounge	19720200-009SF	4/26/2021	19
Women's Staff Bathroom	19720200-010BF	4/26/2021	1
Men's Staff Bathroom	19720200-011BF	4/26/2021	1
Boys Bathroom SE Hall 1	19720200-012BF	4/26/2021	53
Boys Bathroom SE Hall 2	19720200-013BF	4/26/2021	48
Boys Bathroom SE Hall 3	19720200-014BF	4/26/2021	36
Boys Bathroom SE Hall 4	19720200-015BF	4/26/2021	33
Girls Bathroom SE Hall 1	19720200-016BF	4/26/2021	13
Girls Bathroom SE Hall 2	19720200-017BF	4/26/2021	40
Girls Bathroom SE Hall 3	19720200-018BF	4/26/2021	14
Girls Bathroom SE Hall 4	19720200-019BF	4/26/2021	20
Kitchen W	19720200-020KF	4/26/2021	15
Kitchen Middle	19720200-021KF	4/26/2021	33
Kitchen S	19720200-022KF	4/26/2021	13
Kitchen SE	19720200-023KF	4/26/2021	17
Kitchen NE	19720200-024KF	4/26/2021	2
Gym Drinking Fountain	19720200-025DW	4/26/2021	ND
Boys Locker Room N	19720200-026BF	4/26/2021	11

removed from service

Boys Locker Room S	19720200-027BF	4/26/2021	6
Girls Locker Room Middle	19720200-028BF	4/26/2021	3
Girls Locker Room E	19720200-029BF	4/26/2021	5
Girls Locker Room N	19720200-030BF	4/26/2021	<b>33</b>
Room 8 E	19720200-096CF	4/26/2021	ND
Room 8 W	19720200-097CF	4/26/2021	ND
<b>Old Gym</b>			
Gym N Bathroom	19720204-036BF	4/26/2021	<b>15</b>
Gym S Bathroom	19720204-037BF	4/26/2021	8
Stadium Womens Bathroom	19720204-038BF	4/26/2021	<b>18</b>
Stadium Mens Bathroom	19720204-039BF	4/26/2021	6
Stadium Drinking Fountain	19720204-040DW	4/26/2021	ND
<b>Metal Shop</b>			
Room 19 S	19720202-034CF	4/26/2021	7
Room 19 N	19720202-035BF	4/26/2021	7
<b>Wood Shop</b>			
Room 18 NW	19720201-031CF	4/26/2021	6
Room 18 SE	19720201-032CF	4/26/2021	1
Room 18 SW	19720201-033CF	4/26/2021	2
Gym N Bathroom	19720204-036BF	4/26/2021	<b>15</b>

**Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing**

RETESTS			
<b>Main Building and Gym</b>			
Staff Lounge	19720200-009SF	10/21/2021	4.39
Kitchen Middle	19720200-021KF	10/21/2021	11.6
Kitchen SE	19720200-023KF	10/21/2021	5.23
Girls Locker Room N	19720200-030BF	10/21/2021	7.68
<b>Old Gym</b>			
Gym N Bathroom	19720204-036BF	10/21/2021	10.4
<b>Stadium</b>			

Stadium Womens Bathroom	19720204-038BF	10/21/2021	12.7
<b>Main Building and Gym</b>			
Boys Bathroom SE Hall 1	19720200-012BF	3/31/2022	8.32
<b>Main Building and Gym</b>			
Girls Bathroom Middle Hall NW	19720200-006BF	5/4/2022	6.79
Girls Bathroom Middle Hall Middle	19720200-007BF	5/4/2022	2.06
Girls Bathroom Middle Hall NE	19720200-008BF	5/4/2022	4.32
Girls Bathroom SE Hall 4	19720200-019BF	5/4/2022	14.6
<b>Old Gym</b>			
Drinking Fountain Old Gym	19720204-098DW	5/4/2022	6.15
<b>Main Building and Gym</b>			
Boys Bathroom SE Hall 2	19720200-013BF	9/7/2022	4.83
Boys Bathroom SE Hall 4	19720200-015BF	9/7/2022	2.1
Girls Bathroom SE Hall 2	19720200-017BF	9/7/2022	10.8
Kitchen W	19720200-020KF	9/7/2022	11.6
Boys Bathroom SE Hall 3	19720200-014BF	9/27/2022	3.6
			<b>W/ Lead Filter</b>

ND = Non Detect - Lead level is below the set detection lim of 2 ppb